

**Burlington**  
777 Chrysler Drive  
Burlington, WA 98233  
Phone: (360) 755-1990

**Client:**  
Menzel Lake Gravel  
PO Box 1494  
Marysville, WA 98270

**Project:**  
24B108  
Q.C. - Menzel Lake Gravel - 2024  
777 Chrysler Drive  
Burlington, WA 98233

## General Information

<b>Sample Number:</b>	82	<b>Sample Date:</b>	05/30/2024
<b>Sample From:</b>	Not Given	<b>Sampling Method:</b>	Not Provided
<b>Location Details:</b>	Menzel Lake Gravel Pit / Washed 3/4" minus drain rock material		
<b>Material Description:</b>	Not Given	<b>Technician:</b>	Client

## Test Results

<b>Specification:</b>	No Specifications		<b>Variant:</b>	Grad Only Sieves	
Sieve Size	Percent Passing	Percent Retained	Cumulative Fraction Retained	Result	
50 mm (2 inch)	100	0		Pass	
37.5 mm (1.5 inch)	100	0		Pass	
25 mm (1 inch)	100	0		Pass	
19 mm (3/4 inch)	74	26	0.26	Pass	
12.5 mm (1/2 inch)	16	84		Pass	
9.5 mm (3/8 inch)	2	98	0.98	Pass	
6.3 mm (1/4 inch)	1	99		Pass	
4.75 mm (No. 4)	1	99	0.99	Pass	
2.36 mm (No. 8)	1	99	0.99	Pass	
2 mm (No. 10)	1	99		Pass	
1.18 mm (No. 16)	1	99	0.99	Pass	
600 µm (No. 30)	1	99	0.99	Pass	
<b>Fineness Modulus:</b>		0.05			

**Burlington**  
777 Chrysler Drive  
Burlington, WA 98233  
Phone: (360) 755-1990

**Client:**  
Menzel Lake Gravel  
PO Box 1494  
Marysville, WA 98270

**Project:**  
24B108  
Q.C. - Menzel Lake Gravel - 2024  
777 Chrysler Drive  
Burlington, WA 98233

